



*cgc*

PATENT

I hereby certify that on the date specified below, this correspondence is being deposited with the United States Postal Service as first-class mail in an envelope addressed to the Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

April 25, 2007  
Date

Alexandra Beggs  
Alexandra Beggs

**IN THE UNITED STATES PATENT AND TRADEMARK OFFICE**

Applicants :	Jason B. Elledge	Attorney Docket No.:	500188.03
Patent No. :	US 6,932,672 B2	Serial No. :	09/833,029
Issue Date :	August 23, 2005	Filed :	April 10, 2001
Title :	APPARATUS FOR IN-SITU OPTICAL ENDPOINTING ON WEB-FORMAT PLANARIZING MACHINES IN MECHANICAL OR CHEMICAL-MECHANICAL PLANARIZATION OF MICROELECTRONIC-DEVICE SUBSTRATE ASSEMBLIES AND METHODS FOR MAKING AND USING SAME		

**REQUEST FOR CERTIFICATE OF CORRECTION**

Commissioner for Patents  
P.O. Box 1450  
Alexandria, VA 22313-1450

**Certificate**  
**MAY 02 2007**  
**of Correction**

Sir:

A Certificate of Correction under 35 U.S.C. § 254 is respectfully requested for the above-identified patent in order to correct Patent and Trademark Office errors made during the printing of the patent. The changes in the patent needed to correct the errors are as follows:

<u>Column, Line</u>	<u>Reads</u>	<u>Should Read</u>
Column 5, Line 4	"interferrometer"	--interferometer--
Column 7, Line 32	"system in defined"	--system is defined--
Column 8, Line 30	"and a under surface,"	--and an under surface,--
Column 9, Lines 63-64	"a planarizing at zone"	--a planarizing zone--

**MAY - 3 2007**

Column 9, Line 65	"a light source under to the table"	--a light source under the table--
Column 10, Line 24	"and a under surface,"	--and an under surface,--
Column 11, Lines 6-7	"a planarizing at zone at least within"	--a planarizing zone at least within--

The above errors for which correction is requested under 35 U.S.C. § 254 were made in the printing of the patent or in the application. The errors are considered sufficiently important to justify the processing of a Certificate of Correction under 35 U.S.C. § 254. A Form PTO-1050, in duplicate, is enclosed herewith.

The Commissioner is hereby authorized to charge payment of any fees associated with this communication to Deposit Account No. 50-1266. A duplicate copy of this sheet is enclosed.

Favorable consideration of this Request is respectfully requested.

Respectfully submitted,

Date: April 24, 2007

By: Edward W. Bulchis  
 Edward W. Bulchis, Reg. No. 26,847  
 Customer No. 27,076  
 Dorsey & Whitney LLP  
 1420 Fifth Avenue, Suite 3400  
 Seattle, WA 98101  
 (206) 903-8785  
 Attorney for Applicant(s)

EWB:tdp

Enclosures:

Postcard  
 Form PTO-1050 (+ copy)

h:\ip\clients\micron technology\100\500188.03\500188.03 req cert correct.doc

MAY - 3 2007

**UNITED STATES PATENT AND TRADEMARK OFFICE  
CERTIFICATE OF CORRECTION**

PATENT NO. : US 6,932,672 B2  
DATED : August 23, 2005  
INVENTOR(S) : Jason B. Elledge

It is certified that errors appear in the above identified patent and that said Letters Patent is hereby corrected as shown below:

<u>Column, Line</u>	<u>Reads</u>	<u>Should Read</u>
Column 5, Line 4	"interferrometer"	--interferometer--
Column 7, Line 32	"system in defined"	--system is defined--
Column 8, Line 30	"and a under surface,"	--and an under surface,--
Column 9, Lines 63-64	"a planarizing at zone"	--a planarizing zone--
Column 9, Line 65	"a light source under to the table"	--a light source under the table--
Column 10, Line 24	"and a under surface,"	--and an under surface,--
Column 11, Lines 6-7	"a planarizing at zone at least within"	--a planarizing zone at least within--

MAILING ADDRESS OF SENDER:

**DORSEY & WHITNEY LLP**  
1420 Fifth Avenue, Suite 3400  
Seattle, Washington 98101

Patent No. US 6,932,672 B2

No. add'l. copies

@ .30 per page



FORM PTO-1050 (REV. 3-82)

h:\ip\clients\micron technology\100\500188.03\500188.03 pto 1050.doc

MAY - 3 2007

**UNITED STATES PATENT AND TRADEMARK OFFICE  
CERTIFICATE OF CORRECTION**

PATENT NO. : US 6,932,672 B2  
DATED : August 23, 2005  
INVENTOR(S) : Jason B. Elledge

It is certified that errors appear in the above identified patent and that said Letters Patent is hereby corrected as shown below:

<u>Column, Line</u>	<u>Reads</u>	<u>Should Read</u>
Column 5, Line 4	"interferrometer"	--interferometer--
Column 7, Line 32	"system in defined"	--system is defined--
Column 8, Line 30	"and a under surface,"	--and an under surface,--
Column 9, Lines 63-64	"a planarizing at zone"	--a planarizing zone--
Column 9, Line 65	"a light source under to the table"	--a light source under the table--
Column 10, Line 24	"and a under surface,"	--and an under surface,--
Column 11, Lines 6-7	"a planarizing at zone at least within"	--a planarizing zone at least within--

**MAILING ADDRESS OF SENDER:**

**DORSEY & WHITNEY LLP  
1420 Fifth Avenue, Suite 3400  
Seattle, Washington 98101**

Patent No. US 6,932,672 B2

No. add'l. copies  
@ .30 per page



**FORM PTO-1050 (REV. 3-82)**

h:\ip\clients\micron technology\100\500188.03\500188.03 pto 1050.doc

**MAY - 3 2007**